



APPLY HEAT TO FLASHING
AND FORM BY HAND PRIOR
TO HOT AIR WELDING



NOTES:

1. FIELD-FABRICATED PIPE SEAL FOR USE WITH HOT PIPE, 120° F (49° C) OR HOTTER.
2. FLEX TPO NON-REINFORCED MEMBRANE WRAPPED AROUND PIPE SHALL HAVE MINIMUM 1-1/2" (40 mm) VERTICAL HOT AIR WELD.
3. TEMPERATURE OF METAL COLLAR MUST NOT EXCEED 120° F.

TPO 4.05
HOT PIPE FLASHING