



Notes:

- 1) This detail allows the opening to be completed before the stack is in place. The metal sleeve and the clearance necessary will depend on the temperature of the material handled by the stack.
- 2) Vertical wood member may be replaced by an upgraded assembly as shown in detail FLMB-13E02

<p>Flex SBS Modified Roof Systems</p> <p>STACK FLASHING</p> <p>CONVENTIONAL ROOFING ASSEMBLY</p>	Scale: N.T.S.	Plot: 1:5	<p>Flex Membrane International, Inc.</p> <p>2670 Leisch's Bridge Rd.</p> <p>Suite 400</p> <p>Leesport, PA 19533</p> <p>800- 969-0108</p> <p>www.flexmembranes.com</p>
	Date: 8/07	Revision: KF	
	<p>FLMB-10E02</p>		