



Thermoplastic Single Ply and Multi-Ply Roofing Systems

2670 Leiscz's Bridge Road, Suite 400, Leesport, PA 19533 Phone (610) 916-9500 Fax (610) 916-9501

EQUIPMENT AND ACCESSORIES LISTING

The following is a partial listing of equipment and accessories that will assist the applicator in the installation of Flex Single Ply Roofing Systems

GENERAL EQUIPMENT

- Clean, asphalt-free extension cords of adequate sizing to handle power requirements
- One (1) pair of scissors per man
- Tape measures, varying up to 100 feet in length
- Chalk boxes, chalk
- Four inch (4") wide paint brushes
- Clean cotton rags
- Caulking guns
- Push Brooms
- Non-permanent ink or crayon writing element for marking seams
- Several Flex Seam Probes for probing of seams
- Clean, asphalt free waterproof canvas or tarp for covering of materials
- Several one and one-half inch (1 1/2") wide silicon hand rollers
- Several standard screw guns w/ disengaging clutch (1800-2500RPM's)
- One – half inch (1/2") nap paint rollers w/ solvent resistant cores and handles
- Hammers, screwdrivers, sockets, allen wrenches and drill bits
- Utility knife, hook blades, straight blades
- Approved fasteners and plates
- Approved cleaners or solvents
- Approved caulking or sealant
- Wire brushes for cleaning welder tips
- Assortment of tips or nozzles for hand held hot air welder
- Hammer drill or Tapcon Anchor driver
- Notched squeegee for applying substrate adhesive
- 200 pound roller for proper adhesion of Flex FB adhered system

Welding Equipment

- A) Leister Varimat or BAK Laron automatic welding machine, requires 230 volt, 4600 watt power
Leister Triac or BAK Rion hand held hot air welder, requires 120volt, 1600-watt power
- B) Portable Electric Generator: minimum output of 7500 watts to adequately provide power to operate one automatic hot air welder and one hand held hot air welder.